

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

STANDARD ANNULAR PRESSURE TEST

Operator Seiler Tank Truck Service State Permit No. 22954Address 26791 West Michigan Ave USEPA Permit No. MI-075-2D-8002Albion Michigan 49224 Date of Test 7-17-2013Well Name Bissel Center 1-8 Well Type 2D disposalLOCATION INFORMATION SE Quarter of the SE Quarter of the NE QuarterSection 8; Range 2W; Township 4S; County Jackson;Company Representative Joe Van Wagnen; Field Inspector MDEQ Kristy Shimko;Type of Pressure Gauge 4 inch face; 2000 psi full scale; .1 psi increments;New Gauge? Yes ~ No ~ If no, date of calibration 9-27-2012Calibration certification submitted? (Yes) ~ No ~

TEST RESULTS

5-year or annual test on time? Yes ~ (No) ~After rework? (Yes) ~ No ~Newly permitted well? Yes ~ (No) ~

Pressure (in psig)

Time	Annulus	Tubing
<u>8:03</u>	<u>336.6</u>	<u>0</u>
<u>8:13</u>	<u>335.1</u>	<u>0</u>
<u>8:23</u>	<u>334.2</u>	<u>0</u>
<u>8:33</u>	<u>333.5</u>	<u>0</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Casing size 4 1/2Tubing size 2 3/8Packer type 4 1/2" aero set onePacker set @ 1407'Fluid return (gal.) 2.0

Comments:

Test Pressures: Max. Allowable Pressure Change: Initial test pressure x .03 10.1 psiHalf Hour Pressure change 3.1 psi(Test Passed) ~ Test Failed ~

If failed test, well must shut in, no injection can occur, and USEPA must be contacted within 24 hours.

Corrective action needs to occur, the well retested, and written authorization received before injection can recommence.

Joe Van Wagnen
Signature of Company Representative7-17-2013
Date

UNWITNESSED MECHANICAL INTEGRITY TEST FORM